



BALLAST MUST BE GROUNDED

Install lamp within 1" of grounded metal plane
 Insulate unused leads individually for 600V

